

# GIPRO DS-SERIES GEAR INDICATOR Supplementary Manual

Honda CBR1000RR 2004-2007 (GPDT-H01)

Secure the bike on a stand.




Remove the side fairing on the left side.



Locate the diagnostic system connector.

*(Red, 4-pole connector)*




# GIPRO DS-SERIES GEAR INDICATOR

## Supplementary Manual



Honda CBR1000RR 2004-2007 (GPDT-H01)

Connect the Gipro connector to the diagnostic system connector.



Typical position for the Gear Indicator.

Secure the unit properly.

